

**Haworth
Residential
Inspections LLC**

**Wesley Haworth
Owner
Lawton, OK**

racinman486@sbcglobal.net



**Cell: 580-678-4389
580-536-3876
Lic. #757**

**Haworth Residential Inspections
8004 NW Baldwin Ave.
Lawton, OK 73505**

Home Inspection Report



1234 Your Street
Lawton, OKLAHOMA 73507

Haworth Residential Inspections

2016 September 16, 2008

Page 1 of 2
Jm Samplephotosab5



Bricks and mortar piled against wall , possible safety hazard and possible insect



Cracked, broken or missing glass ,north bottom window by garage door .



Torn insulation



Torn insulation



Torn insulation



Non-GFCI circuit by sink. Plug by toilet has ground broken off in it.



Insulation batts have fallen out of position-properly reinstall



Insulation batts have fallen out of position-properly reinstall



Moisture present inside the layers of glass, south window



Both west windows will not open. Window has fogging between the layers of glass, all windows in the sitting area.



Air gap hose improperly connected